



0101seda010100
software engineering dependability

Quality Management of Software and Systems: Supporting Methods and Techniques


- Methods and Procedures
 - Quality Function Deployment (QFD)
 - Statistical Process Control, SPC
 - Reliability Modeling
 - Quality Circles (Qualitätszirkel)
 - Failure Mode, Effects and Criticality Analysis (FMECA)
- Techniques
 - Cause-and-Effect Diagram (Fishbone Chart, Ishikawa-Diagram)
 - Pareto Analysis
 - Quality Control Charts (in terms of SPC)
 - Correlation Diagram

Quality Function Deployment (QFD)

- Complete survey of customer requirements
- Weighting of customer requirements according to their importance for the customer utility and the commercial success
- Tracing of requirements through the development process (transparency which activities are connected with which customer requirements)
- Resources are provided for the realization of important requirements in case of doubt
- Corresponds to the strong customer orientation of TQM, as basically everything can be attributed to customer requirements

Statistical Process Control (SPC)

- Means for differentiating a statistical variation of a process from a systematic one:
 - Accidental dispersion/distribution: production tolerances of a cutter (Frästeil)
 - Systematic change: slow drift of the measure by tool wear, erratic change by clamping of a wrong cutter head
- Uses statistical tools
- Is executed with the aid of the quality control chart



- Production tolerances due to machine accuracy (e.g. lathe)
- Production tolerances due to process accuracy (quality of material, staff member qualification)
- Predefined tolerable variations allow parts to be evaluated with respect to their exceedance: Parts, which are outside tolerable variation limits are rejected.
- Wish to manage with samples as quality control to be able to abandon expensive checking/testing of every work piece (so-called sorting)
- In production the basis of SPC are the so-called machine capability and process capability. They test the general ability of a machine or a process to generate the required tolerance
- Always mixture of systematic influences (e.g. tool wear, increase of fetch) and stochastic dispersion/distribution (machine quality)
- **Application of means of statistics to samples for the separation of noise and real change**

Statistical Process Control (SPC)

Example: Normal Distribution

- Many characteristics are subject to this distribution
- Characteristics

- Sample average value

$$\bar{x} = \frac{\sum_{i=1}^n x_i}{n}$$

- Estimation for the standard deviation


$$s = \sqrt{\frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n - 1}}$$

- Standard deviation





$$\sigma = \sqrt{\frac{\sum_{i=1}^n (x_i - \mu)^2}{n}}$$

Statistical Process Control (SPC)

Normal Distribution



- The inflection points of the curve are at $\mu - \sigma$ and at $\mu + \sigma$
- It can be expected (area below the curve) that approximately
 - 68 % of all measurements are between $\mu - \sigma$ and at $\mu + \sigma$
 - 95 % of all measurements are between $\mu - 2\sigma$ and at $\mu + 2\sigma$
 - 99 % of all measurements are between $\mu - 3\sigma$ and at $\mu + 3\sigma$
- In production besides the mean value \bar{x} of a sampling and the estimation for the standard deviation s also its range R and the median \tilde{x} including the corresponding arithmetic mean/average values $\bar{\bar{x}}, \bar{\bar{s}}, \bar{\bar{R}}, \bar{\bar{\tilde{x}}}$ are used
 - $R = x_{max} - x_{min}$
 - The median concerning an uneven number of measurements is the middle value of the measurements ordered according to size. Concerning an even number of measurements in a sampling the median is the arithmetic mean value of the two middle values
 - The process average value $\bar{\bar{x}}$ is the average value of the sampling average values \bar{x}
- In the scope of SPC the values \bar{x}, \tilde{x}, R, s are presented in so-called quality control charts




- Two different types of control charts depending on the type of information to be depicted:
 - Charts for variable characteristics (measurements). Average/mean value-chart (\bar{x} -chart) combined with distribution-chart (s-chart)
 - Charts for attributive characteristics (countable characteristics (faults) or properties (good/bad))
- Important difference: charts for variable characteristics can reveal trends before problems are generated, charts for attributive characteristics are based on already existent problems (occurred faults)

Statistical Process Control (SPC)

Quality Control Charts

- The basis for the definition of the upper and the lower action control limit is the $\pm 3s$ -interval which represents an appropriate compromise between false alarm and unrealized alarm situation



Statistical Process Control (SPC)

Quality Control Charts for Variable Properties

- The measurements x of properties of a unit, which emanate from a controlled process are normally subject to a normal distribution which is characterized by
 - its average/mean value μ and
 - its variance σ^2
- According to the central limit theorem for a random variable, generated by the overlap of many small factors independent of each other, a normal distribution can be assumed
- Collection of such values in SPC
 - \bar{x} -charts (also called X-charts) for the average/mean value
 - R-charts or s-charts for the distribution

- X-charts serve for the presentation of measurements. They show a displacement of the process average/mean value (e.g. drift) also if the distribution is retained and they identify "outliers/mavericks". X-charts do not serve primarily for the detection of changes of the distribution

$$\bar{x} = \frac{\sum_{i=1}^n x_i}{n}, s = \sqrt{\frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n-1}}$$

- Upper Control Limit: UCL: $\bar{x} + 3s$
- Lower Control Limit: LCL: $\bar{x} - 3s$

Statistical Process Control (SPC)

Quality Control Charts for Variable Properties

Example of a Quality Control Chart: The X-Chart

- Example

- The execution time of a time-critical routine is measured to see if it varies only statistically or if there are systematic influences

no.	1	2	3	4	5	6	7	8	9	10	11	12	13	14
time (ms)	7,5	7,9	8,2	8,1	7,3	16,9	8,1	7,7	6,6	8,0	7,4	8,3	11,8	7,0


$$\bar{x} = \frac{7,5 + 7,9 + 8,2 + 8,1 + 7,3 + 16,9 + 8,1 + 7,7 + 6,6 + 8,0 + 7,4 + 8,3 + 11,8 + 7,0}{14} = \frac{120,8}{14} = 8,6$$

$$s = 2,7$$

Statistical Process Control (SPC)

Quality Control Charts for Variable Properties

Example of a Quality Control Chart: The X-Chart



- X-chart: $UCL = \bar{x} + 3s = 16,7$, $LCL = \bar{x} - 3s = 0,5$
- Point 6 is above the UCL: cause analysis required

- Probability that a unit remains functional under predetermined conditions during a particular period of time (in a way: time-referenced quality)
- Reliability is a statistical value which can be estimated when corresponding failure models are taken as a basis
- Typically expressed as
 - Mean failure-free operating time up to failure (MTTF, Mean Time To Failure)
 - Failure rate $\lambda_{(t)}$: relative failure number per time unit as function of the time. If $\lambda_{(t)} = \lambda$ is constant it is valid

$$MTTF = \frac{1}{\lambda}$$

- Group of few staff members which meets regularly with the aim to solve quality problems occurring in their work area resp. to introduce improvements actively
- Typically weekly meetings of about an hour within the working time
- Realization of improvements normally is done by the group itself after a corresponding license is granted; likewise the control of success/result checking
- Quality circles should apply appropriate methods for the problem identification, analysis and solution (Pareto-diagram, Ishikawa-diagram, brainstorming, ...)
- Support and participation of the top management is essential

Quality Circles

Typical Procedure of Quality Circles

Problem identification, problem selection

- Selection of problems to be analyzed
- Application of creativity techniques for the problem identification
- Prioritization of problems (e.g. with Pareto-diagram)

Problem handling

- Authorization by decision making department
- Coordination with other quality circles
- Separation of primary causes and secondary causes (e.g. with Ishikawa-diagram)
- Define goals
- Search for solutions (e.g. with brainstorming)
- Evaluate alternatives and choose solutions

Presentation of results

- Present solution to the decision making circle and prepare realization

Quality Circles

Typical Procedure of Quality Circles

Introduction and control of success


- Introduce solution
- Documentation of problem, way of solution and result
- Control of success (preferably quantitatively)
- Generalization (transmission to other parts of the organization, ...)

- Method that aims at risk prevention by identifying the failure modes of a system their causes and related effects
- Risk evaluation with the aid of the risk priority number
 - $RPN = \text{occurrence probability} * \text{weight of the effects} * \text{probability of non-detection}$
- Development of proposals for measures
- Decision of measures
- Analysis of residual risk (recalculation of the **Risk Priority Number**)
- Execution of cost benefit analysis

Cause-and-Effect-Diagram (Fishbone Chart, Ishikawa-Diagram)

- Graphical technique for the analysis of cause-and-effect interrelations. To a problem (effect) the primary causes are identified which are further refined into secondary causes etc.
- Defined by Ishikawa for the application in quality circles (Ishikawa-diagram)


Cause-and-Effect-Diagram (Fishbone Chart, Ishikawa-Diagram) Example



Cause-and-Effect-Diagram (Fishbone Chart, Ishikawa-Diagram) Example


- Procedure
 - Define problem (effect) and attach it to the head of the "fishbone"
 - Attach the major causes to the "sidewise fishbones" (often used: the 6 m: man, machine, method, material, milieu, measuring)
 - Attach minor causes to the branches of the "sidewise fishbones" (brainstorming: identification with the aid of the questions: what, why, how, who, when, where)
- Identification of real cause
- Development of solution alternatives and choice of the optimal solution
- Introduction of solution

- The Pareto Principle
20 % of the defect causes generate 80 % of the defects
- Histogram (bar chart/diagram) which presents subsets ordered according to decreasing size from left to right
- Additionally a sum curve of the bar heights can be applied
- Aims at high efficiency concerning improvements by prioritization
- Example: Every bar symbolizes a certain type of error. The height of the bar symbolizes the total costs required for the elimination of faults. The Pareto Principle here is "20 % of the faults cause 80 % of the costs". The avoidance of these 20 % of faults will have first priority. These faults are the aim of quality improvements



- Instrument for the analysis of the dependence between two characteristics based on a set of pairs of characteristics
- Statistical basis: correlation coefficient
- Examples
 - Number of software modules and development costs
 - Number of test cases and number of notified failures during the first year of product use

Correlation Diagram



- Feigenbaum A.V., Total Quality Control, 3rd Edition, New York: McGraw-Hill 1983
- Frehr H.-U., Total Quality Management: Unternehmensweite Qualitätsverbesserung, München: Hanser 1993
- Braverman J.D., Fundamentals of Statistical Quality Control, Reston: Reston Publishing Co., Prentice Hall 1981
- Wheeler D.J., Chambers D.S., Understanding Statistical Process Control, Knoxville: SPC Press 1992
- Zultner R., Before the house: The voices of the customers in QFD, in: Transactions 3rd Symposium on QFD, Novi, MI, June 1991, pp. 450-464